

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403830634

Date Received:  
06/20/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
CAERUS		COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302310  
Inspection Date: 06/11/2024 FIR Submit Date: 06/17/2024 FIR Status:

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334179

Location Name: BATTLEMENT MESA-67S95W Number: 34NWNW County:  
Qtrqtr: NWN Sec: 34 Twp: 7S Range: 95W Meridian: 6  
W  
Latitude: 39.399540 Longitude: -107.988371

FACILITY - API Number: 05-045-00 Facility ID: 334179

Facility Name: BATTLEMENT MESA-67S95W Number: 34NWNW  
Qtrqtr: NWN Sec: 34 Twp: 7S Range: 95W Meridian: 6  
W  
Latitude: 39.399540 Longitude: -107.988371

CORRECTIVE ACTIONS:

4 CA# 195954

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 06/22/2024

Response: CA COMPLETED Date of Completion: 06/19/2024

Operator Comment: Repaired Separator door

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Terry Martinez

Signed: \_\_\_\_\_

Title: COGCC.inspections@caeruso

Date: 6/20/2024 9:52:13 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403830644	Repaired separator door
-----------	-------------------------

Total Attach: 1 Files