

Inspection Photos

June 12th, 2024

Operator: BMG Drilling Corporation - 7650

Location ID: 325388

Inspection Document #: 714000836

La Plata County, CO

Township: NENE 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the southern edge of the project area taken from the center of the disturbance.

API #: 067-06291

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388



6/12/24

+37.136493,-107.952431

27° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the northern portion of the project area taken from the center of the disturbance. Note: area has been seeded and hydro mulched.

API #: 067-06291

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388



Photo 3. View of the access road which has been seeded and hydromulched. Note: access road does not appear recontoured/graded.