

Inspection Photos

06/19/2024

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 335987

Inspection Doc: 696205927

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 335987



Photo 1: Photos 1-2 provide an overview of the Location. Photos also show (5) blue stock tanks stored on the working pad surface and interim areas. Tanks are not necessary for production and require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 335987



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 335987



Photo 3: Photos examples of Noxious Weeds (Bull thistle, Houndstongue) observed on the Location and access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources