

Inspection Photos
Location Name: TEP Rocky Mountain LLC TRANT Pad
Location # 335081



Photo # 948 From entrance to location



Photo # 949 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC TRANT Pad
Location # 335081




Photo # 950 Location



Photo # 951 Location

Location Name: TEP Rocky Mountain LLC TRANT Pad
Location # 335081

Location # 335081



Jun 21, 2024 at 12:35:22 PM

Photo # 953 Sign weathered/faded & starting to become illegible

Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad

Location # 335081



Photo # 7725 From inspection 708903198 conducted on 02/28/2024 Unused Equipment/ECD disconnected



Photo # 954 Unused Equipment/ECD disconnected

Inspection Photos
Location Name: TEP Rocky Mountain LLC TRANT Pad
Location # 335081




Photo # 7726 From inspection 708903198 conducted on 02/28/2024 Unused Equipment/ECD disconnected



Photo # 955 Unused Equipment/ECD disconnected

Inspection Photos

Location Name: TEP Rocky Mountain LLC TRANT Pad

Location # 335081



Photo # 956 Sign weathered/faded & starting to become illegible