

Inspection Photos
Location: Camenisch 1 SX Flowline
Spill ID: 479713 & 482375



Photo 1 –

Photo 2 –



Inspection Photos
Location
Facility ID:



Photo 3 –

Photo 4 –



Inspection Photos

Location

Facility ID:



Photo 5 – Fencing down

Photo 6 – Fencing down



COLORADO
Energy & Carbon Manageme
Commission
Department of Natural Resources

Inspection Photos

Location

Facility ID:



Photo 7 – Fencing down

Photo 8 – Trash in excavation



Inspection Photos
Location
Facility ID:



Photo 9 –



Photo 10 –



Inspection Photos
Location
Facility ID:



Photo 11 –



Photo 12 –



Inspection Photos
Location
Facility ID:



Photo 13 – Signage worn



Photo 14 – Weeds



Inspection Photos

Location

Facility ID:



Photo 15 –

