

Inspection Photos

June 18th, 2024

Operator: Catamount Energy Partners LLC - 10464

Location ID: 438700

Inspection Document #: 714000865

La Plata County, CO

Township: NWSE 3 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Carpenter 32-6-3 2, 1S
Location ID: 438700

6/18/24
+37.046153,-107.484671
194° S



Photo 1. View of the well disturbance from the access point facing center.



API #: 067-09914, 09918

Inspection Photos

Location Name: Carpenter 32-6-3 2, 1S

Location ID: 438700



Photo 2. Seeding/hydro mulch activities conducted in 2022 appear unsuccessful, minimal vegetation establishment observed in interim reclamation areas on the western edge of the disturbance.

Inspection Photos

Location Name: Carpenter 32-6-3 2, 1S

Location ID: 438700



Photo 3. Large patch of field bindweed observed in the western interim reclamation area.