

# Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326199

Inspection Document #: 714000870

La Plata County, CO

Township: SENE 9 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Tubbs 32-6-9 B1  
Location ID: 326199

6/18/24  
+37.035267,-107.500031  
272° W




Photo 1. View of the well disturbance taken from the access point facing center.



Inspection Photos  
Location Name: Tubbs 32-6-9 B1  
Location ID: 326199



**Photo 2.** View of surface owner equipment that remains stored in the western portion of the disturbance.



Inspection Photos  
Location Name: Tubbs 32-6-9 B1  
Location ID: 326199



**Photo 3.** Stained soils at pump jack muffer identified in the previous inspection doc #712700823 has been addressed/resolved.