

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977




Photo 1 – Separators – East Side




Photo 2 – Unmarked Risers at 31-34-15HNB

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 3 – Tank Battery – East Side



Photo 4 – Tank Battery Signs – Tank Labels

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 5 – East Side of East Tanks



Photo 6 – Tank Labels on 3rd Tank from the North

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 7 – F-J-15HNB Wellhead



Photo 8 – Wellhead Sign

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 9 – Wellheads



Photo 10 – Maintenance Tank

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 11 – ECDs



Photo 12 – Tank Battery – West Side

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Energy and Carbon Management Commission
40.40643, -104.31591, 4649.0ft
06/24/2024 12:55:56



Energy and Carbon Management Commission
40.40657, -104.31594, 4653.4ft
06/24/2024 12:56:09

Photo 13 – Tank Battery Signs

Photo 14 – Tank Battery – West Side

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 15 – Separators



Photo 16 – Risers marked

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Photo 17 – Instrumental Air Unit



Photo 18 – Compressor

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Energy and Carbon Management Commission
40.40681, -104.31512, 4637.9ft
06/24/2024 12:57:38



Energy and Carbon Management Commission
40.40711, -104.31446, 4636.4ft
06/24/2024 12:58:27

Photo 19 – Gas Lift Injection Meter House

Photo 20 – Signs at Entrance