

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 1 – Separators



Photo 2 – Tank Battery

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Energy and Carbon Management Commission
40.40534, -104.32435, 4722.0ft
06/24/2024 13:01:35



Energy and Carbon Management Commission
40.40524, -104.3241, 4719.7ft
06/24/2024 13:01:56

Photo 3 – Tank Battery Signs

Photo 4 – Tank Battery – Tank Labels have been updated

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Energy and Carbon Management Commission
40.40618, -104.31379, 4643.4ft
06/24/2024 12:51:33



Energy and Carbon Management Commission
40.40535, -104.32508, 4711.9ft
06/24/2024 13:02:52

Photo 5 – East Side of East Tanks

Photo 6 – Pumping Units

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 7 – 31-34-16HNB Wellhead

Photo 8 – Wellhead Sign missing

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 9 – 41-44-16HNB Wellhead

Photo 10 – Wellhead Sign

Inspection Photos
Location Name: Antelope F-15 PAD
Location ID: 429977



Energy and Carbon Management Commission
40.40661, -104.32546, 4726.2ft
06/24/2024 13:07:48

Photo 11 – Signs at Entrance