

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 6/18/2024



Location Entrance – Photo #01772



Wellheads – Photo #01773

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 6/18/2024



Separators – Photo #01775



Tank Battery – Photo #01776

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 6/18/2024



ECD – Photo #01777



Pneumatic/Heating Equipment – Photo #01788

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 6/18/2024



Insufficient Erosion Control/Degradation/Debris – Photo #01779



Insufficient Erosion Control/Degradation/Debris – Photo #01780

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 6/18/2024



Insufficient Erosion Control/Degradation/Debris – Photo
#01781



Insufficient Erosion Control/Degradation/Debris – Photo
#01785