

KPK  
McCallum 113  
Location ID: 324680



Location



Well signage lacking information

KPK  
McCallum 113  
Location ID: 324680



Weeds around equipment



Pump jack guard missing and weeds around equipment

KPK  
McCallum 113  
Location ID: 324680



Well head leaking



Well head leaking