

Final Reclamation Inspection

June 13, 2024

Operator: NOBLE ENERGY INC - #100322

Location ID: 427188

Inspection Document #: 697505351

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BALL RANCH/AC15-03 TANK
Location ID: 427188



Photo 1. Photo taken of the associated off-location tank battery, facing South. Photo illustrates the Operator has failed to remove all equipment per Rule 1004 and an active, open remediation project.

