

## Inspection Photos


Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Entrance to location - Photo #02936



Location - Photo #02963

## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Well head and chemical tank - Photo #02939



Well head and chemical tank - Photo #02940



## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Separator - Photo #02944



Separators - Photo #02945

## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



PSD not capped and open to wildlife - Photo #02948



Tank battery - Photo #02954





## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Open ended load line - Photo #02976



Open ended load line - Photo #02980

## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Thief hatch open to wildlife/atmosphere - Photo #03000



Thief hatch open to wildlife/atmosphere - Photo #03001



## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Jun 25, 2024 at 1:12:17 PM  
+39.280252,-107.913641 ±4.83m



Jun 25, 2024 at 1:24:24 PM  
+39.280209,-107.913797 ±4.75m

Thief hatch open to wildlife/atmosphere - Photo #03007

Debris - Photo #03016



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location: Laramie Energy LLC Hawxhurst/17-04 pad

Location ID: 422420

Date: 6/25/2024



Northwest corner of location - Photo #03011

