

Inspection Photos

API: 011-06126

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/26/2024

County: Bent



Inspection Photos



Photo 1. Facing south toward the location. The sign posted at meter shed is faded and not legible. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-06126 | Date: 6/26/2024

Inspection Photos



Photo 2. Facing toward the tank battery. There is insufficient secondary containment to contain a spill. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-06126 | Date: 6/26/2024