

KPK  
McCallum 19  
Location ID: 324580




Lacking information on well signage



Lack of battery signage



KPK  
McCallum 19  
Location ID: 324580



Lack of battery signage



Debris





KPK  
McCallum 19  
Location ID: 324580



Belt guard is missing



Load line missing cap/plug