

Inspection Photos

API: 099-06881

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/26/2024

County: Prowers



Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. Facing toward the open top tank where deceased birds were previously observed. The berm has been built up better for secondary containment and netting has been placed over the tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06881 | Date: 6/26/2024

Inspection Photos



Photo 3. Netting nor covers the tank to prevent wildlife entry. There is still no labels on the tank..

