

# Inspection Photos

June 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325572

Inspection Document #: 714000883

La Plata County, CO

Township: SSWSW 32 33N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Carlson 32-01 1  
Location ID: 325572

6/18/24  
+37.056277,-107.529655  
11° N



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Carlson 32-01 1  
Location ID: 325572

6/18/24  
+37.056435,-107.529711  
16° N



**Photo 2.** View of the western interim reclamation area facing north.

Inspection Photos  
Location Name: Carlson 32-01 1  
Location ID: 325572



**Photo 3.** View of rill erosion forming on the cut slope on the eastern side of the disturbance. Storm water BMPs are needed in this area.