

Operator: BCEI

Location Name: State Antelope P-16 Pad

Loc ID: 432999

Inspection: 696306465



Exhibit A

CA: 31-34-16HNB Missing Wellhead Sign, Install sign to comply with Rule 605.d.

CA Resolution: Operator has reported that the missing WH sign has been recovered and re-installed to comply with Rule 605.d