

**Operator: CPR**

**Location Name: Lussing Trust 4-64 19-20 North**

**Loc ID: 486500**

**Inspection: 713900705**



**Exhibit A**

**CA:** At the time of inspection the Operator has failed to install wildlife BMP's on surface casings. Install covers or ramps on surface casings per Rule 406.

**CA Resolution:** Operator has reported as of 6/25, the cellars have been appropriately covered to comply with Rule 406.