

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: ZIEGAL # 7-1

Location ID: 334514 API #: 05-077-08390

Inspection Date: 6/26/2024 Inspection Doc#: 693807464



Injection wellhead inside housing



Pump Housing.

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: ZIEGAL # 7-1

Location ID: 334514 API #: 05-077-08390

Inspection Date: 6/26/2024 Inspection Doc#: 693807464



Tank battery



Separators

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: ZIEGAL # 7-1

Location ID: 334514 API #: 05-077-08390

Inspection Date: 6/26/2024 Inspection Doc#: 693807464



Tank battery



Location overview looking N