

**Inspection Photos**  
**Location Name: Reider 4N67W 18Y Pad**  
**Location ID: 439811**



Energy & Carbon Management Commission  
40.30626, -104.92601, 1456.7m, 194°  
07/02/2024 12:16:53

**Production facility**



Energy & Carbon Management Commission  
40.30795, -104.9253, 1450.2m, 246°  
07/02/2024 12:18:39

**Wellheads**

**Inspection Photos**  
**Location Name: Reider 4N67W 18Y Pad**  
**Location ID: 439811**



**Damaged sound wall**



**Trash**

**Inspection Photos**  
**Location Name: Reider 4N67W 18Y Pad**  
**Location ID: 439811**



**Trash**



**Trash in alfalfa field**