



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #1 concrete pit and
flowlines going to the pit
complet

Jul 2, 2024 1:59:47 PM
40.30752394348383N 107.68887215293944W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #2 monitoring well
broken. Note flowlines at
top of photo, these
flowlines are seen in
photo# 1

Jul 2, 2024 1:59:56 PM
40.30750814359635N 107.68884130753577W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #3 pothole near
fence on east side of
concrete pit.

Jul 2, 2024 2:00:49 PM
40.30720392242074N 107.68888430669904W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #4 combustors

Jul 2, 2024 2:00:53 PM
40.30719080474228N 107.68889771774411W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo # Pothole

Jul 2, 2024 2:01:07 PM
40.30714218970388N 107.68888321705163W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #6 Sign at tank
battery

Jul 2, 2024 2:01:35 PM
40.30701667070389N 107.68896552734077W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #7 chemical tank
inside tank battery

Jul 2, 2024 2:01:46 PM
40.30693381559104N 107.68895655870438W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jul 2, 2024 2:01:55 PM
40.30694144312292N 107.68892889842391W

Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #8 EDW stored
inside tank battery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #9 equipment
stored inside tank battery

Jul 2, 2024 2:02:10 PM
40.30684542842209N 107.68892311491072W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #10 Pothole inside
tank battery



Jul 2, 2024 2:02:25 PM
40.306795723736286N 107.68888229504228W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #11 behind main
u-tube tanks.
Hydrocarbon staining on
ground.

Jul 2, 2024 2:02:37 PM
40.3067352483049N 107.68886209465563W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #12 Pothole inside
tank battery

Jul 2, 2024 2:02:51 PM
40.30665050726384N 107.68886771053076W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #13 behind tank
battery.

Jul 2, 2024 2:02:57 PM
40.30663399491459N 107.68889813683927W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #14 Area of spill
486930. Note pooled
water. This spill is still
open in the ECMC
database. Spill requires
delineation for Table
915-1.

40 30627897940576N 107 68888330087066W
Jul 2, 2024 2:03:42 PM



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jul 2, 2024 2:04:06 PM
40.30609679874033N 107.68890400417149W

Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #15 Area of spill
486930. Note pooled
water. This spill is still
open in the ECMC
database. Spill requires
delineation for Table
915-1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #16 south side of
tank battery.

Jul 2, 2024 2:04:10 PM
40.306099858134985N 107.68890475854278W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #17 Front of tank
battery. Photo taken from
access road.

Jul 2, 2024 2:04:57 PM
40.30625157058239N 107.68907641991973W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #18 Front of tank
battery. Photo taken from
access road.

Jul 2, 2024 2:05:18 PM
40 30642386060208N 107 68906560726464W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #19 Front of tank
battery. Photo taken from
access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/2/2024

Photo #20 South side of
Cement pit



Jul 2, 2024 2:06:17 PM
40.30699294991791N 107.68904733471572W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources