



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#1 Pit facility from
access road

40.309236072935164N 107.68753892742097W
Jul 2, 2024 1:50:42 PM



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#2 Pit facility from
access road

Jul 2, 2024 1:50:47 PM
40.30918825417757N 107.68749282695353W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#3 Pit facility from
outside

Jul 2, 2024 1:53:11 PM
40.30770817771554N 107.68901162780821W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#4 Pit facility

Jul 2, 2024 1:53:13 PM
-40.307702561840415N 107.6890245359391W





Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#5 inside pit
complex, electrical

Jul 2, 2024 1:54:16 PM
40.30760223045945N 107.68922134302557W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#5 piping and hoses inside pit complex

Jul 2, 2024 1:54:24 PM
40.30755441170186N 107.68922058865428W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#7 area of two small pits inside main pit complex.





Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#8 Close up of
photo #7

Jul 2, 2024 1:54:54 PM
40.30743807088584N 107.68921815790236W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#9 Inside pit
complex, liner material
has been blown around.

Jul 2, 2024 1:55:12 PM
40.307380110025406N 107.68919418565929W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#10 piled liner
material.

Jul 2, 2024 1:55:19 PM
40.307337027043104N 107.68919661641121W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#11 inside pit
complex

Jul 2, 2024 1:55:41 PM
40.30742629431188N 107.68940909765661W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#12 main pit

Jul 2, 2024 1:55:54 PM
40.3074633423239N 107.68949492834508W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#13 main pit, fluid
was 85% covered in oil.

Jul 2, 2024 1:55:57 PM
40.30746615026146N 107.68949819728732W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#14 west side of pit
complex

Jul 2, 2024 1:56:07 PM
40.30745035037398N 107.68959517590702W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#15 soil inside pit
complex

Jul 2, 2024 1:56:20 PM
40.30745181720704N 107.6896630693227W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#16 inside pit complex. Evidence of soil migration to the pit.

Jul 2, 2024 1:56:44 PM
40.30741648748517N 107.68982014618814W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#17 area on the west side of pit complex, formerly seen hoses stored in this area.

Jul 2, 2024 1:57:22 PM
40.30734993517399N 107.69008006900549W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#18 previously noted gap in fence. Gap in fence is still present.

Jul 2, 2024 1:57:30 PM
40.3073269687593N 107.69011703319848W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#19 Rock pile in the access road to discharge area.





Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#20 north of main
pit complex, access road
to discharge. Note
hydrocarbon

Jul 2, 2024 2:09:14 PM
40.30825438443571N 107.68924556672573W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#21 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:09:38 PM
40.308217126876116N 107.68946466967463W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#22 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:09:46 PM
40.30821620486677N 107.68950490280986W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#23 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:09:51 PM
40.30822567641735N 107.68952057696879W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#24 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:10:01 PM
40 30821616295725N 107 68957707099617W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#25 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:10:07 PM
40 30820241663605N 107 68958520144224W



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#26 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:10:30 PM
40.308110299520195N 107.6897185575217W



Inspection Photos
Location Name: Iles
Location ID: 116587
Remediation Project #: 28244
Inspection Date: 7/2/2024

Photo#27 Apparent hydrocarbons are visible and hydrocarbon staining observed at the toe of the large Pit Facility embankment, outside of the pit complex

Jul 2, 2024 2:10:39 PM
40.30809068586677N 107.68976105377078W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources