

Inspection Photos

June 26th, 2024

Operator: Nuevada Resources LLC - 10764

Location ID: 484496

Inspection Document #: 714000911

La Plata County, CO

Township: Lot 3 18 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ardourel 33081718 3HL, 4HL
Location ID: 484496



6/26/24
+37.100990,-107.767880
27° NE

Photo 1. View of the well disturbance taken from the access point facing center.



6/26/24
+37.100321,-107.768089
23° NE

NOEVIDA RESOURCES LLC
OPERATOR NO. 10764
ARDOUREL 33081718 PAD
FACILITY ID: 484496
NWSU-SIC: 18-133N-ROSW
LA PLATA CO., CO
PHONE # 214-838-2168
LOCAL # 303-550-8880

NOEVIDA RESOURCES LLC
ARDOUREL 33081718 WELL PAD
FACILITY ID: 484496
EMERGENCY COMPANY CONTACT #'S
PRIMARY: 505-508-5283 (24 HOUR)
SECONDARY: 303-550-8880
EMERGENCY SERVICES ONLY
LA PLATA COUNTY EMERGENCY MANAGEMENT
376-280-8170
FIRE DEPARTMENT - JORNADO, CO
376-563-9091

Inspection Photos

Location Name: Ardourel 33081718 3HL, 4HL

Location ID: 484496



6/26/24

+37.101068,-107.766604

146° SE

TOP
SOIL



Photo 2. View of top soil pile covered in annual weeds, including but not limited to Cheatgrass and Lambs quarter. Note: All disturbed areas observed on the location were covered in annual weeds.

Inspection Photos

Location Name: Ardourel 33081718 3HL, 4HL

Location ID: 484496



Photo 3. Musk thistle observed in patches around the well pad disturbance.

Inspection Photos

Location Name: Ardourel 33081718 3HL, 4HL

Location ID: 484496



Photo 4. View of functioning and maintained storm water BMPs along existing access road separating the well and tank pads.

Inspection Photos
Location Name: Ardourel 33081718 3HL, 4HL
Location ID: 484496

6/26/24
+37.099929,-107.765887
168° S



Photo 5. View of tank pad top soil pile that is covered in annual weeds, including but not limited to Cheatgrass and Lambs quarter.

Inspection Photos

Location Name: Ardourel 33081718 3HL, 4HL

Location ID: 484496



Photo 6. View of functioning and maintained storm water BMPs along the perimeter of the tank pad.

Inspection Photos
Location Name: Ardourel 33081718 3HL, 4HL
Location ID: 484496



Photo 6. Additional view of delineation between reference area (Left) and disturbed area (right) where annual weeds have moved in and are dominating disturbed areas.

Inspection Photos
Location Name: Ardourel 33081718 3HL, 4HL
Location ID: 484496



Photo 7. Additional view of musk thistle establishing in the tank pad disturbed areas.