

# Final Reclamation and Stormwater Inspection

Date: 06/26/2024

Operator: PDC ENERGY INC - 69175

Location ID: 305231

Inspection Document #: 708201371

Adams County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: J&L Farms 41-19  
Location ID: 305231



**Photo 1.** Facing north. The well location (Location ID 305231 with API 123-22685) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Well location and access road appear reflective of adjacent reference area cropland. This location is "In-Process" - Operator will need to submit a Form 44 off location flowline abandonment notice and the site will be re-inspected at a later date.



Inspection Photos  
Location Name: J&L Farms 41-19  
Location ID: 305231



**Photo 2.** Facing east; see comments in Photo 1.

Inspection Photos  
Location Name: J&L Farms 41-19  
Location ID: 305231



**Photo 3.** Facing south; see comments in Photo 1.



Inspection Photos  
Location Name: J&L Farms 41-19  
Location ID: 305231



**Photo 4.** Facing west; see comments in Photo 1.