

Operator: BCEI
Location Name: Antelope 42-19 RTB
Loc ID: 418214
Inspection: 696306479



Exhibit A

CA: Northeast 300 BBL Tank - NFPA Label; see photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has reported that NFPA label has been installed to comply with Rule 605.h.