

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: ANTELOPE 42-19 RTB

Loc ID: 418214

Inspection: 696306479



Exhibit A

CA: Unmarked Risers at Separators; see photos. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

CA Resolution: Operator has reported that identified risers have been appropriately marked to comply with Rule 1105.b.