

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Entrance to location - Photo #03088



Location - Photo #03099

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Well heads - Photo #03092



Well heads - Photo #03093

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Separators - Photo #03094



Separators - Photo #03095

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Jun 27, 2024 at 2:01:10 PM
+39.192044,-107.910777 ±4.67m
Collbran

Tank battery - Photo #03097



Jun 27, 2024 at 2:09:39 PM
+39.192616,-107.911169 ±4.70m

Northwest corner of location - Photo #03107

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Open to wildlife - Photo #03106



Debris - Photo #03109

Inspection Photos

Location: Laramie Energy LLC YT Ranch/17-5 Pad

Location ID: 334537

Date: 6/27/2024



Debris - Photo #03110