

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 6/27/2024



Location Entrance – Photo #02050



Wellheads – Photo #02051

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 6/27/2024



Separators – Photo #02055



Tank Battery – Photo #02053



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 6/27/2024



Tank Battery – Photo #02056



Pit – Photo #02052

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 6/27/2024



Spill Response – Photo #02057



Open-Ended Load Line – Photo #02054