

Final Reclamation and Stormwater Inspection

Date: 7/2/24

Operator: Bayswater Exploration & Production LLC -
10261

Location ID: 319523

Inspection Document #: 713900754

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Chandler #1
Location ID: 319523



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates crop in the disturbance (Red) has not yet met reference areas (Blue).

Photo 2. The photo was taken at the tank battery location facing West. The photo illustrates the boundary and discrepancy between the disturbed area and reference in the field.

Inspection Photos
Location Name: Chandler #1
Location ID: 319523



Photo 3. The photo was taken east of the well location facing West. The photo illustrates the well and access road appear to continue to meet Rule 1004 standards.