

**Operator: EXTRACTION OIL & GAS INC**

**Location Name: Arellano 10-L Pad**

**Loc ID: 440761**

**Inspection: 708201214**



Exhibit A



**Exhibit B**



**Exhibit C**

**CA:** This location does not comply with Rule 1003. During this inspection, it was observed that interim areas do not appear to be progressing towards reclamation/vegetative standards with evidence of undesirable vegetation (e.g. kochia) throughout. Refer to FIR (#708201212) for additional reclamation comments at Location (#440766). Refer to attached inspection photos for additional. Comply with Rule 1003. Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards.

**CA Resolution:** Operator has reported that the location has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Operator also noted that the location was sprayed prior to interseeding actions to address weeds/additional undesirable vegetation. Location currently complies with Rule 1003.