

# Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 7/15/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 7/15/2024



## Inspection Photos



**Photo 2.** Facing northwest toward the access road. The side of the road needs to be seeded and stabilized



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 7/15/2024



## Inspection Photos



**Photo 3.** Facing northwest toward the location. The sign has fallen over and the silt fence is down and not maintained.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 7/15/2024



## Inspection Photos



**Photo 4.** The sign has fallen over and the silt fence is down and not maintained.





## Inspection Photos



**Photo 5.** Facing toward the soil stock pile. The topsoil has not been seeded and stabilized and weeds are beginning to establish.





## Inspection Photos



**Photo 6.** Facing toward the backside of the soil stock pile. There is erosion occurring along the topsoil pile and the silt fence is in disrepair.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 7/15/2024



## Inspection Photos



**Photo 7.** Facing toward the wellsite.





## Inspection Photos



**Photo 8.** North side of the location facing east. The silt fence is down and not maintained.

