Work Completion Report
Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
WARNER 4-18 WEED MITIGATION		Dusty Hayden	7/17/2024

Work Summary		Reclamation Type	Land Use
Weed eated weeds around well heads and filled in the pot holes with dirt		Final Maint	Crop

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Facility Weed Control	High	Yes	Location(s): WARNER 4-18 WP Notes: Weed whack weeds around well head, assess pot holes for weed mitigation. WALK INTO LOCATION. MUST BE COMPLETED BY 7/18, THIS IS A CORRECTIVE ACTION. PLEASE GET COMPLETION REPORT IN ASAP.

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
Seed Mix: **None used**
Crop Type: **Alfalfa**
Soil Type: **Sandy Loam**
Stabilization Date: **7/17/2024**
Seeding Date: **7/17/2024**
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: WARNER 4-18 WP
COGCC ID: **305848**
Well APIs at Location: **12323565**
Land Rep:
Land Owner:
Rec Contractor PO(s
Vendor PO(s):
Billing Notes:
Legal Address: **(WELD) NWNW 18 2N65W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes:
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Pre-Completion
Description:

Photo Name: Post-Completion
Description:

Photo Name: A
Description:

Photo Name: B
Description:

Photo Name: C
Description:

Photo Name: D
Description:

Photo Name: E
Description:

Photo Name: F
Description:

Photo Name: G
Description:

Photo Name: K
Description:

Photo Name: L
Description:

Photo Name: M
Description:

Photo Name: N
Description:

Photo Name: O
Description:

Photo Name: P
Description:

Photo Name: Q
Description:

Photo Name: S
Description:

Photo Name: T
Description:

Photo Name: U
Description: