

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/36B-795

Location ID: 324310

Date: 7/17/2024



Wellhead – Photo #02276



Separator/Methanol Tank – Photo #02282

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/36B-795

Location ID: 324310

Date: 7/17/2024



Tank Battery – Photo #02279



Damaged/Unserviceable Fencing – Photo #02281