

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROCK 19-05 Pad

Location ID: 335155



Photo # 2969 From entrance to location



Photo # 2970 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROCK 19-05 Pad

Location ID: 335155



Photo # 2971 Location



Photo # 2972 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROCK 19-05 Pad

Location ID: 335155



Photo # 2973 Location



Photo # 2974 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROCK 19-05 Pad

Location ID: 335155



Photo # 2975 Barbed wire fence needs maintenance/barbed wire laying on the ground/wildlife hazard (E/NE area of location near entrance to location)



Photo # 2976 Barbed wire fence needs maintenance/barbed wire laying on the ground/wildlife hazard (E/NE area of location near entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROCK 19-05 Pad

Location ID: 335155



Photo # 2977 Barbed wire fence needs maintenance/barbed wire laying on the ground/wildlife hazard (E/NE area of location near entrance to location)



Photo # 2978 Small amount of staining near wellhead