

Inspection Photos

07/18/2024

Operator: ANSCHUTZ EXPLORATION CORP -
3104

Location ID: 315979

Inspection Doc: 696205991

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 315979



Photo 1: BMPs at the soil stockpile(s) have not been installed or maintained in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 315979



Photo 2: BMPs at the soil stockpile have not been installed or maintained in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 315979



Photo 3: Photos 3-4 taken from the soil stockpiles on the west end of the Location. Photos examples showing weeds (Halogeton) continue to establish on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 315979



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources