

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403830060

Date Received:
06/19/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205852

Inspection Date: 05/30/2024

FIR Submit Date: 06/11/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335939

Location Name: SG Number: L27 496 County: _____

Qtrqtr: NWS Sec: 27 Twp: 4S Range: 96W Meridian: 6
W

Latitude: 39.671713 Longitude: -108.159793

FACILITY - API Number: 05-045-00 Facility ID: 335939

Facility Name: SG Number: L27 496

Qtrqtr: NWS Sec: 27 Twp: 4S Range: 96W Meridian: 6
W

Latitude: 39.671713 Longitude: -108.159793

CORRECTIVE ACTIONS:

1 ☒ CA# 195806

Corrective Action: Comply with 603.i

Date: 06/26/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator
Comment: Replaced caps/plugs

ECMC Decision: Approved

ECMC Representative:	
-------------------------	--

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Nick Croy	Signed: _____
Title: Compliance	Date: 6/19/2024 2:32:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403830060	FIR RESOLUTION SUBMITTED
403830065	Replaced caps/plugs

Total Attach: 2 Files