

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403843250
Receive Date:
07/03/2024
Report taken by:
Chris Sanchez

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>BNL (ENTERPRISE) INC</u>	Operator No: <u>10763</u>	Phone Numbers Phone: <u>(970) 7595370</u> Mobile: <u>()</u>
Address: <u>2011 FOREST AVENUE</u>		
City: <u>DURANGO</u>	State: <u>CO</u>	Zip: <u>81301</u>
Contact Person: <u>Peter Kondrat</u>	Email: <u>pkondrat@bluestarhelium.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 33145 Initial Form 27 Document #: 403593107

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>481042</u>	API #: _____	County Name: <u>LAS ANIMAS</u>
Facility Name: <u>Enterprise State 16-1 (2962)</u>	Latitude: <u>37.518290</u>	Longitude: <u>-104.337470</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NESE</u>	Sec: <u>16</u>	Twp: <u>29S</u>	Range: <u>62W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Residential Building Unit 2,010 to the South

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

--

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|---|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input checked="" type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input checked="" type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	Not impacted	visual
No	SOILS	Not impacted	visual
No	SURFACE WATER	Not impacted	visual
No	VEGETATION	Not impacted	visual

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Collected sample of drill cuttings.
Two soil sample adjacent to wellhead will be taken and sent to an appropriate lab.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Two soil sample adjacent to wellhead using soil auger and will be sent to an appropriate lab. Please see sample location diagram.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 8

Highest concentration of TPH (mg/kg) _____

Number of soil samples exceeding 915-1 0

Highest concentration of SAR _____

Was the areal and vertical extent of soil contamination delineated? Yes

BTEX > 915-1 _____

Approximate areal extent (square feet) 100

Vertical Extent > 915-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? No

Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) _____

Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed _____

Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 _____

Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Attachments include (2) background virgin soil samples E16-BG1 and E16-BG2.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 45

Volume of liquid waste (barrels) 0

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soils found near the excavation of the P&A wellhead have been segregated and readied to for disposal at the Trinidad Landfill. The drill cutting are in-situ and ready for excavation and then disposal at the Trinidad Landfill.

Attachments include (2) impacted wellhead soil samples E16-WH1 and E16-WH2; (2) non-impacted wellhead samples taken after impacted material removed E16-WH3 and E16-WH4; (2) background virgin soil samples E16-BG1 and E16-BG2 & (2) impacted cuttings trench soil samples E16-CT1 and CT2. The (8) total soil samples attached exhibits include sample identification, Timestamp Camera Basic documentation, location information and laboratory analytical results.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Soil and groundwater was not impacted.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Yes Excavate and offsite disposal

Chemical oxidation
 Air sparge / Soil vapor extraction
 Natural Attenuation
 Other _____

If Yes: Estimated Volume (Cubic Yards) 40
Name of Licensed Disposal Facility or ECMC Facility ID # _____
 Excavate and onsite remediation
 Land Treatment
 Bioremediation (or enhanced bioremediation)
 Chemical oxidation
 Other _____

Groundwater Remediation Summary

Bioremediation (or enhanced bioremediation)
 Chemical oxidation
 Air sparge / Soil vapor extraction
 Natural Attenuation
 Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Final reclamation

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

The operator carries a general liability policy that has \$1 million of coverage per occurrence with a \$2 million aggregate limit along with an additional \$4 million umbrella policy.
The operator intends to cover the estimated cost of the remediation from cash on hand.
BNL (Enterprise) Inc Certificate of Insurance attached.

Operator anticipates the remaining cost for this project to be: \$ _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards 45

E&P waste (solid) description Impacted wellhead soil & drill cuttings

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: Trinidad Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The well was plugged and abandoned on 04/07/2023 and a subsequent Form 6 was approved. This included the GPS coordinates of the as-drilled location. During final reclamation the cellar was removed and backfilled. All debris, and surface equipment was removed. There were no flowlines on this location that needed to be abandoned and reclaimed. The well had no hydrocarbon shows or flows during the drilling, testing or encountered during plugging and abandoning. No production facilities were ever installed on this location. The access road was closed, graded and recontoured. The topsoil was taken from the stockpile and redistributed evenly across the area and the surface was reconstructed to original contours. Then the location was seeded using a Colorado State Land Board (surface owner) approved seed mix with the assistance of the local NRCS office. The seed mix was broadcast-seeded at twice the application rate shown and covered 0.25 to 0.5 inches deep. No noxious weeds were found in the disturbed areas prior to reclamation. An intensive weed monitoring control program is being implemented along with the stormwater management plan.

May 2024 remediation operations includes exposing P&A's wellhead and cuttings trench. Impacted soils from both locations were identified and readied for commercial disposal. Then after the site is cleared of impacted soils it will be closed, graded and recontoured. Then the location will be reseeded in newly disturbed areas.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? No

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? Yes

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 04/10/2023

Proposed date of completion of Reclamation. 04/14/2023

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 04/06/2023

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/27/2023

Proposed site investigation commencement. _____

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Peter Kondrat

Title: Chief Operating Officer

Submit Date: 07/03/2024

Email: pkondrat@bluestarhelium.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Chris Sanchez

Date: 07/24/2024

Remediation Project Number: 33145

COA Type

Description

	This Form is being approved at this time. For all future submittals, Operator shall include historical and recent soil analytical data in a table format along with Photo Logs of all areas sampled.
	After a review of the Analytical Data supplied it appears there were impacts to soil from a historical spill at the wellhead. The Operator shall report the Spill or Release on a Form 19, Spill/Release Report, pursuant to Rule 912.
	Operator shall continue Quarterly Reporting until the Site Assessment is completed and the remediation area demonstrates Compliance with Table 915-1 Standards. Previously assigned COAs shall apply
	Impacted soil will be segregated for proper offsite disposal and the lateral and vertical extent of impacts shall be determined with appropriate confirmation soil sampling
4 COAs	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

403843250	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
403843887	MONITORING REPORT
403843888	SOIL SAMPLE LOCATION MAP
403843889	PHOTO DOCUMENTATION
403843894	OTHER
403843895	ANALYTICAL RESULTS
403844187	MAP
403864096	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 8 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)