

Final Reclamation and Stormwater Inspection

Date: 07/23/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 457004

Inspection Document #: 708201429

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 1. Taken from the southeast corner of the former tank battery location. The disturbance area is predominantly undesirable vegetation (e.g. kochia).

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 2. Taken from the southwest corner of the former tank battery. See comments in Photo 1.

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 3. Taken near the center portion of the former tank battery location. See comments in Photo 1.

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 4. Taken on the western edge of the form tank battery location. Red outline illustrates approximate area of the location that has not been recontoured or graded to reflect adjacent topography.

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 5. Taken from the northeast corner of the former tank battery location. See comments in Photo 1.

Inspection Photos

Location Name: Howard T6N R64W S27 L01

Location ID: 457004



Photo 6. Taken from the western edge of the former tank battery. Red line shows reference area (right) and the disturbance area (left).