


**Inspection Photos**  
**Location Name: Winder South 9-E Pad**  
**Location ID: 446906**



**Lease road entrance sign**



**Wellheads**

**Inspection Photos**  
**Location Name: Winder South 9-E Pad**  
**Location ID: 446906**



**Weeds at SW exterior corner of fencing**



**Weeds at south exterior of fencing**

**Inspection Photos**  
**Location Name: Winder South 9-E Pad**  
**Location ID: 446906**



**Weeds on location**



**Weeds along the lease road entrance**