

Inspection Photos

ID: 333545

Operator: OGRIS OPERATING LLC

Inspection Date: 7/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road There are orange cones that have fallen over around this open hole. The open hole should be closed. There is also unused pipe at red arrow that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:333545 | Date: 7/22/2024

Inspection Photos



Photo 2. The access road thru the location needs to be maintained and stabilized with BMP's such as gravel.



Inspection Photos



Photo 3. Facing southeast at the location. This area does not appear to be establishing vegetation and may need additional seeding performed.



Inspection Photos



Photo 4. Facing southwest at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:333545 | Date: 7/22/2024

Inspection Photos



Photo 5. There are undesirable weeds (Kochia) that will need to be controlled.

