

# Inspection Photos

API: 071-08322

Operator: OGRIS OPERATING LLC

Inspection Date: 7/22/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-08322 | Date: 7/22/2024



## Inspection Photos



**Photo 2.** There is oil leaking out of the engine that has spilled at the concrete base.

