

Inspection Photos

API: 071-08748

Operator: OGRIS OPERATING LLC

Inspection Date: 7/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. There is oil in the engine skid that has spilled over onto the ground and has mixed with stormwater..



Inspection Photos



Photo 3. There is oil in the engine skid that has spilled over onto the ground and has mixed with stormwater..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources