


**Operator: *CRESTONE PEAK RESOURCES OPERATING LLC***  
**Location Name: LIBERTY 63N68W / 21 NENW 2-21 BATTERY**  
**Loc ID: 424387**  
**Inspection: 694100401**



Exhibit A



**Exhibit B**

**CA:** Orange construction fencing around the open excavation is falling down, needs to be resecured. Install or repair required BMP's per Rule 1002.f(2)C

**CA Resolution:** Fence has been resecured to comply with Rule 1002.f(2)C