

Inspection Photos

API: 071-09013

Operator: WAPITI OPERATING LLC

Inspection Date: 7/29/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. There is erosion along the roadside which needs BMP's to control erosion. Tip: Rocks could be utilized to create check dam structures for erosion control.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09013 | Date: 7/29/2024

Inspection Photos



Photo 2. Facing toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. There is a deep erosion channel at the north side of the location.

