

# Inspection Photos

API: 071-06815

Operator: WAPITI OPERATING LLC

Inspection Date: 7/29/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** The gas line is closed and has a plug in it.





## Inspection Photos




**Photo 3.** Further along the road another gas line with valve has no plug or lock to prevent accidental opening.





## Inspection Photos



**Photo 4.** Facing northeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources