

Inspection Photos

July 29th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325256

Inspection Document #: 714001005

La Plata County, CO

Township: NWNE 7 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Long and Schluter 3
Location ID: 325256



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Long and Schluter 3
Location ID: 325256



Photo 2. View of the western interim reclamation area facing north.

Inspection Photos
Location Name: Long and Schluter 3
Location ID: 325256



Photo 3. Reference area comprised Sagebrush and Crested wheatgrass.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06014