

# Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-16 (I8E) Pad

Location #: 334907




Photo # 3854 From entrance to location

Photo # 3855 Location

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC COUEY 8-16 (I8E) Pad**  
**Location #: 334907**



**Photo # 3856 Location**



**Photo # 3857 Location**

Inspection Photos  
Location Name: CAERUS PICEANCE LLC COUEY 8-16 (I8E) Pad  
Location #: 334907



Photo # 3858 Location

Photo # 3859 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-16 (I8E) Pad

Location #: 334907



Photo # 3860 Debris




Photo # 3861 Tank label damaged & some required info is illegible