

**Operator: *CRESTONE PEAK RESOURCES OPERATING LLC***

**Location Name: BRANCH-64N65W 23SWSW**

**Loc ID: 332679**

**Inspection: 714201321**



**Exhibit A**

**CA:** Overgrown vegetation inside tank battery berm. See attached photo. Comply with Rule 606.

**CA Resolution:** Weeds have been removed to comply with Rule 606.