

Operator: *Extraction Oil & Gas LLC*
Location Name: Winder South 9-E Pad
Loc ID: 446906
Inspection: 697009830




Exhibit A




Exhibit B




Exhibit C




Exhibit D

CA: Weeds are growing along the lease road and outside of the location fencing, see attached photos. Comply with Rule 606

CA Resolution: Vegetation has been mowed and line trimmed around this location in order to comply with Rule 606.